

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 26

Township: 7 North


Range: 1 East

Corner ID: Polk U-21

Monument Description & Remarks: 3" Brass Disk stamped, "T7N R1E, S.26/S.25, S.35/S.36, 1973 SO143". Survey Sign 5ft above ground at pt. D

References On File: Andrew J. Sobiech description of original monument, Certified Land Corner Restoration (1973), on file in Surveyor Office

RECOVERY TIE DRAWING
Field Book 41 Page No. 73




Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 27th day of October, 2008.

Kevin P. Enright

Administered by the Monroe County Surveyor Review Board

Date: 4-7-2009



CERTIFIED LAND CORNER RESTORATION

State of Indiana }
County of Monroe } ss.

[U-21]

I, Andrew J. Sobiech, do hereby certify that on the 26th day of June, 1973, I found evidence of the Section corner of Section 25, 26, 35, 36 Township 7 North, Range 1 East, Second Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:

Original monument was a wood post set in 1814	Subsequent survey by J. Spencer, county surveyor filed in Monroe Co. His bearing tree was:	New witness tree recorded by Co. surveyor in 1878:
Original bearing trees:		
Beech Beech	Beech	W.O. R.O.
6" 12"	14"	18" 3"
S 43° E N 66° W	N 28° W	N 03° W S 31° W
24 lks 22 lks	14 lks	7 lks 40 lks

Description of corner evidence found:


Found sandstone 3" x 12" x 18" long planted along an old wire fence running east and west. There is a small open field south and west of stone.

Description of monument and accessories I established to perpetuate the original location of this corner:

I replaced the stone with a 2" I.D. by 3 ft. long concrete filled galvanized iron pipe, capped with a 3" Di. brass tablet stamped to identify the corner. I established the following witnesses:

Maple	Hickory	Pignut	Sign Post
6"	14"	10"	4"x4"
S 18° W	S 40° W	N 70° W	N 48° E
18.9'	10.9'	15.6'	7.2'

I laid the old stone on top of the mound beside the new monument.



Field Assistant Henry Deaton & Ron Overshiner, U.S.F.S.
~~Resident witnesses~~

Dated at Brownstown Indiana, this 26th day of June, 1973.

Signature Andrew J. Sobiech Title R.L.S.
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. S-0143

Index No. V-21
(Alphabetical-Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 806-924T. 7N R. 1E 2nd Mer. N.F. Koozer County Monroe State La.
Section Corner common to sections 35, 36, 25 and 26

EXISTING SURVEYS

Original Government Survey

Year surveyed 1814
Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Beech Beech
Diameter 6" 12"
Bearing S 43 E N 66 W
Distance 24 lks 22 lks

Subsequent Corner Restoration

Year surveyed 1859 By J. J. S. Sponler
Where filed or recorded No. Co. Survey 85 75 10'
Monument
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Beech
Diameter 14"
Bearing N 25 W
Distance 14 lks

Original Evidence Found

Year of search 1972 By H. Denton - B. Aynes
Monument found No

Original Bearing Trees Found


Species _____
Diameter _____
Bearing None
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1972 By H. Denton - Bob Aynes

Bearing Trees, Reference Objects

None



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections 26 36
 Object corner 26-36
 Record distance 15 ch S
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. old wire fence runs E-W remains of fence in still in trees. Stone is about 50' south of Pine plantation.
(Did not chain N to creek)
USA owns all adjacent lands

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Found Stone along old wire fence running E-W

New witness trees recorded in 1878 Monroe County Surveyor
W.O 18" R.O 3"
N 3° E S 31 W
7 Iks 40 Iks

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

At time of search:

1. Did you have the record description?

Yes ☒ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. Maps Photos

3. Man hours spent in search 1 hr

4. Do you think additional search might recover evidence? Yes _____ No ☒

5. Signature J. H. Denton